

SAFE HOME LEADSAFE CHARLOTTE

CITY OF CHARLOTTE HOUSING & NEIGHBORHOOD SERVICES

BID OPENING CERTIFICATION RECORD

Date of Bid Walk: 1/21/2021 Bid Due Date: 1/29/2021 HNS: 21-31

Public Body Estimate

PBE +15%	\$24,392
PBE -15%	\$18,029
PBE	\$21,210
Address	2500 Pitts Dr

Bid Results

Bidder	Contractor	Amount	Projected Start Date	Projected Finish Date
١.	AVM	\$21,350	3/15/2021	4/19/2021
1_:	Yeshua	\$22,350	2/22/2021	3/26/2021
3.	JP Builder	\$25,050	3/1/2021	4/21/2021
4.	Schultz	\$21,220	3/1/2021	3/25/2021
5.				
6.				

Bids Opened By: Elízabeth Lamy

Bids Recorded By: Elízabeth Lamy

Date: 1/29/2021



TLC by CLT

CITY OF CHARLOTTE

HOUSING & NEIGHBORHOOD SERVICES

Company Acknowledgement:	
provisions of the housing improvement of through the City of Charlotte Housing & inspected the site in all particulars, hereby put time stated and in strict accordance with the and all labor and materials, and to do all wood advised respective contractual, for the sur	ment necessary for the completion of the Work shown
Specs Dated:	Number of Pages:
Addenda # 1 Dated: 1/27/2021	Number of Pages: 12
Addenda # 2 Dated:	Number of Pages:
Project Schedule: (A DATE must be included \[\sqrt{N} \include Completion Deadline: (please provide project) \[\text{MATE must be included} \]	d here or the bid will be nonresponsive) A

Please Print and Sign:	
Company Name/Firm: Self Pm S	- 2
Authorized Representative Name: 8 2/5ch	- co
Signature: Date:	

GENERAL REQUIREMENTS

All Contractor's Project Requirements

The contractor is responsible for all project requirements, including but not limited to:

All activities required by the City's COVID-19 Precautions for Residential Housing Rehabilitation Activities policy.

Obtaining all permits required. Said permits shall include all items in this scope of work.

Provide temporary toilet facilities from job start until the completion of work.

Provide AS MANY roll-off dumpsters as needed without damaging the site. Collect construction debris using dust control methods. Remove dumpsters and repair any evidence of the dumpster use.

Bid Cost:

Base

Quantity

Quantity

Contractor may haul debris away daily using dump trailers or trucks.

Custom Hardwood Floor Repair - Various Loca			GENERAL	REQUIREMENTS
Spot repair damaged hardwood flooring in both loc - Living Room - underneath front right window (un - Middle Bedroom - just beyond doorway from the ***Price to include repair/replacement of affected of	dining room damaged hardwood flooring		r as close as poss	sible.
If any structural repair is required, it will be address	sed via Change Order.			
	Bid Cost:	x		1200
Baseboard Install		Base	Quantity	Total Cost
Install wooden baseboards free of surface defects, shall be painted white to match existing.	fastened with finished nails	, properly set ar	KITCHEN and puttied. Newly	installed material
				motalieu material
				2
			=_ Quantity	300 Total Cost
tchen Exhaust Fan - New Installation		×	=	300

Bid Cost:

Refurbish Existing Gravel Driveway

EXTERIOR

Exterior

Fill as necessary any ruts/holes in existing gravel driveway and grade a few inches lower to add additional gravel as needed to properly cover driveway in 4" deep of gravel. Driveway is approximately 12' wide, and 40+' long.

***Contractor responsible for verifying driveway dimensions.

	Bid Cost: _	W. Hart	_x	= 450
		Base	Quantity	Total Cos
ght Fixture Exterior - Relocate			EXTERIO)P -
elocate or remove and replace existing securit stallation of gutters.	ty light at the rear left side of t	the home to a	location suitable t	o accommodate the
	Bid Cost: _		x	= 250
		Base	Quantity	Total Cost
Exterminate Termites			OFNED AL	ESCHEROLO.
Exterminate Termites Exterminate for termites. Drill and patch foundaryear guarantee with an optional yearly renewable			nator must be licer	
Exterminate for termites. Drill and patch founds	ation and pavement where nece ble warranty for the homeowner Bid Cost:		nator must be licer	nsed and provide a 1
Exterminate for termites. Drill and patch foundated year guarantee with an optional yearly renewable see Attached Lead Scope	Bid Cost:	X Base	nator must be licer = Quantity	Total Cost
Exterminate for termites. Drill and patch founda year guarantee with an optional yearly renewab	Bid Cost:	X Base	Quantity GENERAL R	Total Cost

Repoint Masonry Bricks

EXTERIOR

Exterior

Rake out existing mortar joints to a minimum depth of 1/2". Completely fill mortar joints to match existing.



400 Bid Cost: _ Quantity **Total Cost**

Vinyl Window

Contracto

Contact

EXTERIOR

Exterior

Dispose of window units and any security bars. Field measure, order and install new Energy Star rated vinyl, double glazed LOW- E windows including half screens. Insulate rough opening. Install new extension jambs, casing and sill as needed, prime and paint. Exterior trim to be wrapped in PVC coated aluminum coil as needed. Repair all areas disturbed by removal and installation. This installation is to include repairing any damaged header, framing (to include king studs, jack studs etc.) sub-floor, floor joists, band joists and sill. Any windows replaced in a bathroom must have tempered glass. ***Bathroom window is to remain. 500



Base Quantity **Total Cost**

Broken Tile Repair - Front Porch

EXTERIOR

Re-install "broken tile" that has come loose from the front porch, right in front of the front door. Owner has the loose tiles. Re-grout



Bid Cost: 00 Quantity **Total Cost**

Repaint/Refinish Metal Security Doors

EXTERIOR

Exterior

Remove rust and deteriorated paint, prime and repaint metal security door on front and left side porches.



Bid Cost: Quantity

Specification

0.4				*	
Aluminum	Gutter	8	Downspout	5 -	Install

EXTERIOR

Exterior

type .027 gauge seamless aluminum gutter to service roof with sufficient pitch to downspouts. White or brown color choice



tom Awning Repaint

EXTERIOR

Exterior

p and paint metal awnings above front left window, front porch, and right side entry stoop white.



pair Window Frame - Rear Face (Kitchen Wall)

EXTERIOR

Exterior

wrap exterior window components with white aluminum and caulk/weatherproof the window itself, as well as where it intersects brick addition. Add any missing grout or mortar along where the two brick walls intersect.



g Repair - Rear Face (Kitchen Wall)

EXTERIOR

etal flashing where missing/repair is needed at all junctions of roof with walls. Flashing shall be corrosion-resistant, solid al metal or step flashing and blind-nailed.



Finish Repair

BEDROOM

air wall finish. Patch drywall or plaster holes in wall	greater than one inch. All others use an adhesive mesh and mud over the
h with the appropriate material. Wet sand smooth.	Paint new repair to match.

Replace foundation vent housing with heavy duty galvanized steel screening. ***Contractor responsible for counting number of vents needed. Only replace vents if damaged. Re-install/re-secure vents if they are simply loose. Existing vents that are in good condition are to remain. Bid Cost:		Bid Cost: _		X .	= 400,€
Aceplace foundation vent housing with heavy duty galvanized steel screening. **Contractor responsible for counting number of vents needed. Only replace vents if damaged. Re-install/re-secure vents if they are simply loose. Existing vents that are in good condition are to remain. **Bid Cost: x = 400.			Base		
Bid Cost: X = 400. Cleaning Exterior Brick Bid Cost: X = 400. Cleaning Exterior Brick Cleaning Exterior Brick Cleaning Exterior Brick Bid Cost: X = 400. Cleaning Exterior Brick Bid Cost: X = 400. Cleaning Exterior Brick Exterior Exterior Brick Bid Cost: X = 400. Cleaning Exterior Brick Brick Exterior Brick Brick Exterior Brick	oundation Vent Screen - Entire House			FVTTDIA	10000
Bid Cost: X = 400. Cleaning Exterior Brick Cleaning Exterior Brick Clean moss, algae, salt crystals, and any other soil from exterior brick surfaces of the home by using an appropriate environmentally-safe brick/masonry cleaner applied with a natural or synthetic bristle brush. Do not use a wire brush. Bid Cost: X = 400. Exterior Exterior Bid Cost: X = 400. Exterior Exterior Bid Cost: X = 400. Exterior Base Quantity Total Cost EXTERIOR Exterior Exterior Base Quantity Total Cost Base Quantity Total Cost Base Quantity Bid Cost: X = 400. Exterior Base Quantity Total Cost Base Quantity Total Cost Base Quantity Bid Cost: X = 400. Exterior Base Quantity Total Cost Base Quantity Total Cost Base Quantity Bid Cost: X = 400. Exterior Base Quantity Total Cost	Replace foundation vent housing with heavy duty galvanized	steel screening			Exter
Cleaning Exterior Brick Clean moss, algae, salt crystals, and any other soil from exterior brick surfaces of the home by using an appropriate environmentally-safe brick/masonry cleaner applied with a natural or synthetic bristle brush. Do not use a wire brush. Bid Cost: x = 400 \ \frac{\pi}{2} \ Base Quantity Total Cost WI Space Access Door all a 3/4" pressure treated plywood access door in a 2" x 4" pressure treated frame. Provide galvanized iron hinges and hasp. Bid Cost: x = \frac{50}{50}	The state of the s		e vents if dan	naged. Re-install/re-s	ecure vents if they
Cleaning Exterior Brick Clean moss, algae, salt crystals, and any other soil from exterior brick surfaces of the home by using an appropriate environmentally-safe brick/masonry cleaner applied with a natural or synthetic bristle brush. Do not use a wire brush. Bid Cost: x = 400 \ \frac{\pi}{2} \ Base Quantity Total Cost WI Space Access Door all a 3/4" pressure treated plywood access door in a 2" x 4" pressure treated frame. Provide galvanized iron hinges and hasp. Bid Cost: x = \frac{50}{50}		Bid Cost:		x -	4000
Clean moss, algae, salt crystals, and any other soil from exterior brick surfaces of the home by using an appropriate environmentally- safe brick/masonry cleaner applied with a natural or synthetic bristle brush. Do not use a wire brush. Bid Cost:		The same			
Clean moss, algae, salt crystals, and any other soil from exterior brick surfaces of the home by using an appropriate environmentally- safe brick/masonry cleaner applied with a natural or synthetic bristle brush. Do not use a wire brush. Bid Cost:	Cleaning Exterior Brick				
Bid Cost: X = 400.32 Base Quantity Total Cost Total Cost EXTERIOR Exterior all a 3/4" pressure treated plywood access door in a 2" x 4" pressure treated frame. Provide galvanized iron hinges and hasp. Bid Cost: X = \sum_{50}	Clean moss, algae, salt crystals, and any other soil from extended brick/masonry cleaner applied with a natural or synthetic	rior brick surfaces	s of the home		Exterior environmentally-
Base Quantity Total Cost In a 1 square Access Door Fall a 3/4" pressure treated plywood access door in a 2" x 4" pressure treated frame. Provide galvanized iron hinges and hasp. Bid Cost: x = \(\sum_{0.0000} \) Base Quantity Total Cost		-	- Hot doc a will	e blusii.	
all a 3/4" pressure treated plywood access door in a 2" x 4" pressure treated frame. Provide galvanized iron hinges and hasp. Bid Cost: x = _50^-		Bid Cost:	x		
all a 3/4" pressure treated plywood access door in a 2" x 4" pressure treated frame. Provide galvanized iron hinges and hasp. Bid Cost: x = \SSO	The state of the s				400.00
EXTERIOR Exterior all a 3/4" pressure treated plywood access door in a 2" x 4" pressure treated frame. Provide galvanized iron hinges and hasp. Bid Cost: x = _50^-					
Bid Cost:			Base		
Bid Cost: =			Base	Quantity	Total Cost
Raco			Base	Quantity	Total Cost
Base Quantity Total Cost		pressure treated	Base	Quantity EXTERIOR de galvanized iron hing	Total Cost
		pressure treated	Base frame. Provi	Quantity EXTERIOR de galvanized iron hing	Total Cost
		pressure treated	Base frame. Provi	Quantity EXTERIOR de galvanized iron hing	Exterior ges and hasp.

GFCI Receptacle 20 AMP

KITCHEN

Install a flush mounted, ground fault circuit interrupted, duplex receptacle and cover plate. Fish wire and repair all tear out as needed. ***Price is for one change out.



Bid Cost:_ **Total Cost** Base Quantity

Certification

Contractor Name:

Signature:

LEAD ABATEMENT SCOPE OF WORK & INSTRUCTIONS TO BIDDERS 2500 Pitts Dr 8/5/2020

	Complete the following scope of work:		Each	COST
Item#	Feature	Method		NOOD
	Windows A1, A2, B1, B3, C1, C2, C3, C4, D1, D3 and D4 - white wood window sashes and wells	Replace wood sashes and wells with vinyl replacement windows		550
	Side A Porch - white wood ceiling,	Cover with Tyvek and vinyl or aluminum (work includes repair/replacement of rotten wood components)		2100
	Side D - white wood trim/freeze board EXPOSED under the Door D1 awning	Scrape loose paint and repaint		100
	Door A1 - white wood door jambs and 4 stops			800
	4 stops	Replace (newly installed materials are to be painted windy		0 150

- 1 Contractors may submit an occupant protection plan on the form provided. Contact Jim Roy if an additional form is needed
- 2 Complete all interior work in a unit in a single day. Any newly installed materials shall be primed and painted.
- 3 Allow for replacement of 50 board feet of rotted wood.
- 4 Unless otherwise noted any window or door removal and replacement includes frame and trim on both sides.
- 5 In lieu of complete removal, window frames may be enclosed with vinyl on exterior in accordance with all project manual requirements
- 6 Contact Jim Roy to conduct inspections prior to repainting or other putback and after vinyl siding installation.
- 7 Windows being placed in a bathroom need to be tempered glass.

Total Bid

Acknowledgement of Addenda (if any):

Addendum#	Date	
Addendum #1		1/27/2021

The undersigned contractor agrees to perform the scope of work for the indicated fee in accordance with applicable regulations and the project manual. The undersigned also certifies that the work will be completed within 60 days of award.

Signature of authorized contractor representative

Contractor Submitting Bid: Solly Conse.
Address:

Phone: 704 200 6007

Phone: